

ECR #: P6

Tracker #: 9

Status: Ratified

Title: Correction for Key to Pin 1 Measurement in Figures B2 and B3

Release Date: June 2, 1997

Impact: Clarification

Spec Version: NLX 1.2

Summary:

In Figures B2 and B3, the measurement from the key on the NLX riser connector to pin 1 on the connector needs to be corrected from 77.44 [3.049] to 75.50 [2.972].

Background:

On the NLX riser connector, as shown in Figures B2 and B3, the measurement from the key on the connector to pin 1 erroneously shows this as 77.44 [3.049]. The actual measurement is 75.50 [2.972]. The figures need to be replaced with the new figures below.

Change Current Specification As Shown:

Replace Figure B2, NLX Riser Example 1, with the following figure:




Figure B2: NLX Riser Example 1

Replace Figure B3, NLX Riser Example 2, with the following figure:




Figure B3: NLX Riser Example 2